



Facility Assessment Report (FAR)

CONFIDENTIAL

Audit Report No: AU/SIM/FAR10.0003/02

Name of Service Facility and Type (auditee, and Repair Workshop):

Rotary Technical Services Sdn. Bhd.

Address (site(s) audited):

No 3 Jalan P4/8, Bandar Teknologi Kajang
Kajang, Selangor
MALAYSIA

No. of employees

Total and (Ex overhaul/repair services)

65 at this site (15 directly employed in Ex work)

Scope of audit

initial
assessment

reassessment

surveillance ✓

Scope and Description of work performed

(e.g. Repair and Overhaul of Rotating Machines, Enclosures, etc)

Repair and Overhaul of Motors up to 7.5 MW (Ex d, Ex e, Ex n),
Generators up to 400 MW (Ex e, Ex n) and Ex d Terminal boxes of
Generators

Types of protection for the Service Facility Scope:

d, e, n

Responsible persons:

Harban Singh (Ex d, e, n)
Hardeep Singh (Ex d, e, n)
Hairul Helmi Mat Buang (Ex d)
Shubaschander (Ex d, e, n)
Wong Chin Kin (Ex d, e, n)
Sarbeet Singh (Ex d, e, n)

Audit date:

16 & 17 February 2012

Audit Team Leader:

William Rannard

Date of issue:

24 April 2012

Report expiry date:

12 December 2013

Next audit due in:

December 2012

Issued by:

**Safety in Mines Testing and
Research Station (Simtars)**

2 Smith Street REDBANK QLD 4301
Australia

